

Classification	Reference	Date:
EL08-026	ITB08-042	September 3, 2008

G35/G37; IPOD® DISCONNECTS WHILE DRIVING

APPLIED 2007-2008 G35 (V36)
VEHICLES: 2008 G37 (CV36)
APPLIED G35 vehicles built before JNKBV61E(*)8M 223464 / 21 May, 2008
VIN/DATE: JNKBV61F(*)8M 273853 / 21 May, 2008
 G37 vehicles built before JNKCV64E(*)8M 127835 / 21 May, 2008

IF YOU CONFIRM:

That during iPod® operation the iPod® disconnects or the speakers "cut out" while driving.

ACTION:

Replace the Auxillary Audio System Harness with the applicable one from the Parts Information section of this bulletin.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Harn-Aux Audio System	284H2-1BA0A	1 as applicable ⁽¹⁾
Harn-Aux Audio System	284H2-1BA0B	1 as applicable ⁽¹⁾

⁽¹⁾ Reference the Electronic Parts Catalogue (WINFAST) for Part Code **284H2** and use the applicable Part.

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL iPod® Harness (Harn-Aux Audio System)	(1)	RR12AA	HB	32	(2)

(1) Reference the Electronic Parts Catalogue (WINFAST) for Part Code **284H2** and use the indicated Harn-Aux Audio System P/N as the PFP.

(2) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.